

DESIGN ACTIVITY REPORT #02.0 – August 27, 2008

02.01	How much would bleachers cost?	AP
02.02	How many seats can we actually fit?	AP
02.03	Discuss separating power from well with the pg&e rep. - Is the easement adequate?	AP
02.04	Add overhead door to room 303A	SH
02.05	Ensure all cabinets have locks	SH
02.06	Room 304 - Door 304A to be a pair (8'-0") - Add door opposite 304A, pair @ 8'-0" wide for drive thru - Add walk door to north wall	SH
02.07	Building 4 -Widen front open to 10'-0" minimum, maintain number of rooms, it is acceptable to lose a portion of each animal wash. - Omit doors, allow for a gate closure	SH
02.08	Provide 3' to 4' over hangs	SH
02.09	If possible bottom on over hang soffit to be 10'-0"	SH
02.10	All exterior walls are concrete block	FYI
02.11	Due to new code if gas is piped into welding lab, it can't share with another occupancy.	FYI
02.12	Alternate: Use portable welding units to start the welding program and later add dedicated welding building.	
02.13	Rough floor plan for building provided by Richard.	FYI
02.14	AP to put floor plan into Auto Cad and generate several options for Committee to review.	AP

DESIGN ACTIVITY REPORT #03.0 – September 24, 2008

03.01	Would like to have gutters at eaves.	AP
03.02	Omit drains at tack storage slope towards opening.	AP

- | | | |
|-------|--|----|
| 03.03 | Gates at building 4 should be chainlike with slats. | AP |
| 03.04 | Would like to automate sprinklers. | AP |
| 03.06 | Bldg 4: open 10'-0" with gate stopping 6" shorter from CLG. | AP |
| 03.07 | Fluorescent at E&W wall, with cage in each room.
- add dial timer | PK |
| 03.08 | Omit blocks on central spine with screen to allow for ventilation. | AP |

DESIGN ACTIVITY REPORT #04.0 – September 24, 2008
Meeting with David Bigler

- | | | |
|-------|--|----|
| 04.01 | Master Plan for rodeo build out. | DB |
| 04.02 | Current well pump is 900-100gpm
- at some point an additional well, will be required. | DB |
| 04.03 | Add risers & line to irrigate fields in lieu of fenced pasture. | AP |
| 04.04 | Possibly add a well as a bid alternate
- redundancy for ex system
- Could be primarily for rodeo/pasture | DB |
| 04.05 | Possibly a surge tank for rodeo dust control if no VFD. | DB |

ACTIVITY REPORT #05.0 – October 8, 2008

- | | |
|-------|---|
| 05.01 | Make sure food through in project. |
| 05.02 | Move restroom buildings west <ul style="list-style-type: none"> • North building needs to allow for EMS access to 16' gate at arena • Move entry court also |
| 05.03 | Would like entry court behind gate. |
| 05.04 | Do (2) sets of 6 tier bleachers. |
| 05.05 | Need space between chain link fence and north edge of arena support for a tractor to maneuver, |
| 05.06 | Main road east of arena support and horse stalls. |
| 05.07 | No need to fence between spectator area and property line fence. |

- 05.08 Road west of arena and horse stalls doesn't need to be paved.
- 05.09 Would like to get some paving at the central parking of horse stalls.
- 05.10 Site lighting is included in the project.